



CUPRINOL TRADE CLADDING & FENCE OPAQUE

CT678

PRODUCT INFORMATION

Typical Use	<p>Cuprinol Trade Cladding & Fence Opaque is a high performance solvent-based opaque exterior woodstain for the protection and decoration of exterior non-joinery timber such as cladding, garden structures and rough sawn or smooth fencing.</p> <p>Before preparing any surface for painting, read the Health Safety & Environmental information on page 2 about old lead-based paints.</p>
Codes according to the List of Wastes Regulations	<p>Product as supplied: Assigned as hazardous waste code 08 01 11* waste paint and varnish containing organic solvents or other dangerous substances.</p> <p>Part-used containers, containing dried residues of the supplied product: Assigned as hazardous waste code 08 01 11* waste paint and varnish containing organic solvents or other dangerous substances</p> <p>Used containers, rigorously scraped out and containing dried residues of the supplied product: Assigned as non-hazardous waste code 15 01 02 plastic packaging OR non-hazardous waste code 15 01 04 metal packaging.</p> <p>"Rigorously scraped out" means removing the maximum amount of product from the container by physical or mechanical means (draining or scraping) to leave a residue or contamination that cannot be removed by such means.</p> <p>These codes have been assigned based on the actual composition of the product both as supplied and as dried residues. If mixed with other wastes, the waste codes quoted may not be applicable.</p>
Pack Size	10 Litre.
Colour Range	See appropriate Cuprinol Trade colour card.
Composition (nominal)	<p>Pigment: Iron oxide and organic pigments.</p> <p>Binder: Oil modified alkyd.</p> <p>Solvent: Aliphatic hydrocarbon solvent.</p>
Volume Solids	Nominal 47%.
Application Method	Brush or roller.
Drying Times	<p><i>Single coat at standard thickness:</i></p> <p>Touch Dry: 4-6 hours.</p> <p>Recoat: 16 hours.</p>
Practical Coverage	A guide to the practical coverage which can be achieved under normal conditions is up to 12 sq. metres/litre/coat.
Cleaning Up	<p>Remove as much product as possible from application equipment before cleaning with white spirit.</p> <p>Do not use or store in extremes of temperature.</p>

SURFACE PREPARATION

GENERAL

All surfaces must be sound, clean, dry and free from wax, grease, oil etc.

Note. Creosote or similar finishes must be allowed to weather before application of **Cuprinol Trade** Cladding & Fence Opaque. Try a test area to ensure the final appearance is acceptable. Some bleed-through into light colours may occur.

CUPRINOL TRADE CLADDING & CT678 FENCE OPAQUE

PRESERVATIVE TREATMENT

All new work should include treatment with a wood preservative where necessary. Non-durable timbers or timbers containing a significant proportion of sapwood should be preservative treated with **Cuprinol Trade** Wood Preserver Clear ^(BP).

ROUGH SAWN WOOD

Clean weathered and dirty wood using a stiff bristle brush (not a wire brush), detergent and water. Where surfaces are affected by mould or algae, etc, wash with a suitable fungicidal wash. Rinse and allow to dry.

NEW/BARE PLANED WOOD

Natural oils/resins should be removed from oily and resinous timbers using white spirit. If oil or resin levels are high, a stronger solvent such as cellulose thinners or a proprietary brush cleaner may be used. If in doubt first apply **Cuprinol Trade** Cladding & Fence Opaque to a test area to check drying and adhesion are acceptable.

Using an abrasive paper, sand down in the direction of the grain until smooth. Round off sharp edges. Remove dust and loose particles. Clean once more with white spirit and allow to dry thoroughly.

Surfaces should be thoroughly brushed to remove loose particles, wiped with white spirit and allowed to dry.

WEATHERED PLANED WOOD

Completely remove all grey or de-natured wood by sanding or scraping back to a clean, bright surface before applying finish.

PAINTED OR VARNISHED WOOD

If old paint is in sound condition, **Cuprinol Trade** Cladding & Fence Opaque can be applied on top, provided the surface is clean and dry. Sand well before applying over old paint. Ensure flaking or chalky paint is removed by stripping and sanding to a sound surface. Varnish should be completely stripped and the surface treated as for new work.

WOODSTAINED WOOD

Lightly sand and wash surfaces with a mild detergent solution to remove dirt and contamination. Rinse and allow to dry.

Where surface are affected by mould, algae, etc., wash with a suitable fungicidal wash. Rinse well with clean water and allow to dry thoroughly. Spot 'prime' any bare wood with **Cuprinol Trade** Cladding & Fence Opaque.

FILLERS

Use a good quality exterior grade wood filler.

TEST AREA

Carry out a small test to ensure that appearance, drying and adhesion are acceptable prior to large scale application.

SYSTEM INFORMATION

Normally there is no need to stir **Cuprinol Trade** Cladding & Fence Opaque before use but any separated liquid on the surface should be stirred in gently.

Two coats of **Cuprinol Trade** Cladding & Fence Opaque will normally be required to produce a completely opaque finish. Allow the first coat to dry before applying the second.

Cold, humid conditions will retard drying and may affect final appearance and durability. Do not apply below 5°C, in damp conditions or if rain or frost is likely before the finish is fully dry.

KNOTTING

To reduce the risk of knot staining with light shades, a two coat application of an appropriate white shellac knotting is recommended prior to application of **Cuprinol Trade** Cladding & Fence Opaque.

HEALTH, SAFETY & ENVIRONMENTAL INFORMATION

SOLVENT-BASED WOODFINISH

THIS PRODUCT IS FOR EXTERIOR USE ONLY.

Contains 3-iodo-2-propynyl-n-butyl carbamate, ethyl methyl ketoxime. May produce an allergic reaction.

Keep away from sources of ignition - no smoking.

Contains white spirit. Use only in well ventilated areas.

In case of insufficient ventilation, wear suitable respiratory equipment.

Avoid contact with skin and eyes.

When applying it is advisable to wear eye protection.

In case of contact with eyes, rinse immediately with plenty of water and seek medical advice.

After contact with skin, wash immediately with plenty of soap and water or a proprietary skin cleanser. Do not use solvent, thinners or white spirit.

Keep out of the reach of children.

If swallowed, seek medical advice immediately and show this container or label.

Do not use or store by hanging on a hook.

Do not empty into drains or watercourses.

Safety data sheet available for professional user on request.

Avoid the inhalation of dust. Wear a suitable face mask if dry sanding.

Special precautions should be taken during surface preparation of pre-1960s paint surfaces over wood and metal as they may contain harmful lead. For further advice contact ICI Paints Technical Group, at ICI Paints/AkzoNobel, Wexham Road, Slough SL2 5DS.

Tel: 08444 817 818

Issued June 2011

CUPRINOL TRADE CLADDING & CT678 FENCE OPAQUE

See www.cuprinoltrade.co.uk

EU limit value for this product (cat.A/e):500g/l (2007)/400g/l (2010).
This product contains max.399g/l VOC

****Cuprinol Trade** Wood Preserver Clear ^(BP) contains 3-iodo-2-propynyl-n-butyl carbamate, propiconazole.
Use biocides safely. Always read the label and product information before use.

VOC Content High 25% - 50%. VOCs (Volatile Organic Compounds) contribute to atmospheric pollution.

Cuprinol, ICI Roundel and Dulux Trade are Trademarks of AkzoNobel.

© AkzoNobel 2011 (15062011IT SDSCT678)

