



Hammerite Direct To Rust Metal Paint Aerosol Smooth Finish

About this product

Hammerite Direct to Rust Smooth Metal Paint is specially formulated to perform as primer, undercoat and topcoat in one

Key Benefits

- ✓ Direct to rust. Easy to use.
- ✓ Up to 8 years rust protection
- ✓ Ultra tough - excellent weather resistance
- ✓ Smooth glossy finish for a flawless high sheen
- ✓ Solvent based

Special Features

- ✓ Direct to rust

Technical Information

Touch dry	1-2 hours
Recoatable	15 minutes
Coverage	Aerosol - 400ml covers up to 0.5m ²

Product Information

Typical Use

Abrade smooth surfaces and remove all loose and flaking paint with a wire brush. Remove dirt and dust with diluted detergent. Remove grease with Hammerite Brush Cleaner & Thinners. Then rinse with clean water and allow time to dry. Spray a test patch of Hammerite Direct to Rust Metal Paint onto painted surfaces and leave for at least 1 hour. If there is no reaction apply Hammerite Direct to Rust Metal Paint directly to surface. If there is a reaction remove all paint from the surface. On bare zinc, aluminium and galvanised surfaces, apply Hammerite Special Metals Primer before applying Hammerite Direct to Rust Metal Paint

Composition

Solvent-based

Key Benefits

Direct to rust. Easy to use., Up to 8 years rust protection, Ultra tough - excellent weather resistance, Smooth glossy finish for a flawless high sheen, Solvent based

Pack size

400ML

System Information

Store aerosol at room temperature for 2 hours prior to use. Shake can vigorously, in a vertical motion, until the agitator ball is heard and then for a further 3 minutes. Apply light even coats, from a distance of approximately 15cm (6 inches) and keep the aerosol moving. Do NOT concentrate spray in one spot. Apply 3-4 coats for maximum protection and allow 15 minutes between coats. Between coats invert can and spray for 2 seconds to avoid blockages.

Application Method

Store aerosol at room temperature for 2 hours prior to use. Shake can vigorously, in a vertical motion, until the agitator ball is heard and then for a further 3 minutes. Apply light even coats, from a distance of approximately 15cm (6 inches) and keep the aerosol moving. Do NOT concentrate spray in one spot. Apply 3-4 coats for maximum protection and allow 15 minutes between coats. Between coats invert can and spray for 2 seconds to avoid blockages